

4270/4290 VCQ and VRQ Motor Cycle Tracking Sheets

The tracking sheets originally produced for this qualification have recently been reviewed and this has resulted in further clarification being included regarding evidence requirements. In some cases the original information did not provide sufficient clarity and therefore allowed some differences of interpretation, these anomalies have now been addressed.

The tracking sheets for the competency units have now been combined with the relevant short-answer questions to provide individual assessment packs per level and pathway which includes the internally assessed documentation required, these are available to download from the City & Guilds website under 4270.

Some minor format changes have also been made in order to provide further clarity and consistency.

Two things to note:

1. The evidence requirements stated on the tracking sheets indicate the minimum evidence required to meet the assessment criteria. Depending on the situation additional evidence may be required.
2. Candidates completing both the VCQ & VRQ must meet the assessment requirements of both qualifications. For example, if the VCQ requires two observations and the VRQ three observations, then a minimum of three observations must be recorded. However only two of these need to be from the workplace the third can be produced within the centre but must meet current industry practice and standards.

The table below indicates the units where the original evidence may have been misinterpreted.

Unit	NoS	Comment re evidence requirement
001	G1/2	Revised sheet providing improved clarification of evidence requirements
003	G3	No change
004	G4	Working with plastics has been added
006	G6	No change
008	G8	Further clarification on VRQ evidence requirement
301	MC01	No change
302	MC02	No change
303	MC03	VCQ & VRQ evidence is either starting and charging not both
304	MC04	Clarification on observation requirements for VRQ
305	MC05	No change
307	MC07	No change
308	MC08	Clarification on observation requirements for VRQ
312	MC12	Two observations required for VRQ
436	AE06MC	VCQ evidence for six faults in total, to include one each from starting and charging. VRQ observed evidence for five faults, to include one each from starting and charging

All candidates must be using these revised tracking sheets or amended previous versions to show how the Evidence Requirements are being met for both qualifications in full.