

## City & Guilds 6156 Streetworks Excavation and Reinstatement

Product update - January 2016

Changes to Programmes of Study (POS) and unit numbers for 2016

This document has been produced to help you understand the changes that have been made to the Programs of Study (POS) and unit numbers used for City & Guilds Streetworks qualification for 2016.

This is to ensure that the issue of duplicate certification does not re-occur. Please ensure you register all candidates who are taking Streetworks for the first time and those being reassessed using the initial assessment on 6156-23. For those being reassessed using the multiple choice questions please use 6156-24. You will be given automatic approval for these new programmes of study.

The first greyed out columns give the previous numbering and the new 2016 numbering then follows. The last column gives the unit titles which have not changed. Please also note that there have been no changes to the unit content or assessment recording materials at this time.

Centres requiring materials for the old POS can use the documentation for the new units found in the assessment materials section.

The new structure for Streetworks proposed by the Department for Transport, which is expected to be in place for October 2016, will alleviate the need to produce a new version every year.

### 6156-23 Streetworks Excavation and Reinstatement

Post 2015 POS 6156-01 unit numbers	2015 POS 6156-21 unit numbers	2016 POS <b>6156-23</b> unit numbers	Unit title
001	201	<b>221</b>	Location and avoidance of underground apparatus
002	202	<b>222</b>	Signing, lighting and guarding
003	203	<b>223</b>	Excavation in the highway
004	204	<b>224</b>	Reinstatement and compaction of backfill materials
005	205	<b>225</b>	Reinstatement of sub-base and base (roadbase) in non-bituminous materials
006	206	<b>226</b>	Reinstatement in cold-lay bituminous materials
007	207	<b>227</b>	Reinstatement in hot-lay bituminous materials
008	208	<b>228</b>	Reinstatement of concrete slabs
009	209	<b>229</b>	Reinstatement of modular surfaces and concrete footways
010	210	<b>230</b>	Monitoring signing, lighting and guarding
011	211	<b>231</b>	Monitoring excavation in the highway
012	212	<b>232</b>	Monitoring reinstatement and compaction of backfill materials
013	213	<b>233</b>	Monitoring reinstatement of sub-base and base (roadbase) in non-bituminous materials
014	214	<b>234</b>	Monitoring reinstatement in bituminous materials
015	215	<b>235</b>	Monitoring reinstatement of concrete slabs
016	216	<b>236</b>	Monitoring reinstatement of modular surfaces and concrete footways

## 6156-24 Reassessed Streetworks Excavation and Reinstatement

Post 2015 POS 6156-02 unit numbers	2015 POS 6156-22 unit numbers	2016 POS 6156-24 unit numbers	Unit title
101	301	<b>321</b>	Reassessed Location and avoidance of underground apparatus
102	302	<b>322</b>	Reassessed Signing, lighting and guarding
103	303	<b>323</b>	Reassessed Excavation in the highway
104	304	<b>324</b>	Reassessed Reinstatement and compaction of backfill materials
105	305	<b>325</b>	Reassessed Reinstatement of sub-base and base (roadbase) in non-bituminous materials
106	306	<b>326</b>	Reassessed Reinstatement in cold-lay bituminous materials
107	307	<b>327</b>	Reassessed Reinstatement in hot-lay bituminous materials
108	308	<b>328</b>	Reassessed Reinstatement of concrete slabs
109	309	<b>329</b>	Reassessed Reinstatement of modular surfaces and concrete footways
110	310	<b>330</b>	Reassessed Monitoring signing, lighting and guarding
111	311	<b>331</b>	Reassessed Monitoring excavation in the highway
112	312	<b>332</b>	Reassessed Monitoring reinstatement and compaction of backfill materials
113	313	<b>333</b>	Reassessed Monitoring reinstatement of sub-base and base (roadbase) in non-bituminous materials
114	314	<b>334</b>	Reassessed Monitoring reinstatement in bituminous materials
115	315	<b>335</b>	Reassessed Monitoring reinstatement of concrete slabs
116	316	<b>336</b>	Reassessed Monitoring reinstatement of modular surfaces and concrete footways

## 6156-24 Reassessed Streetworks Excavation and Reinstatement (Evolve units)

Post 2015 POS 6156-12 unit numbers	2015 POS 6156-22 unit numbers	2016 POS 6156-24 unit numbers	Unit title
501	601	<b>621</b>	Reassessed Location and avoidance of underground apparatus
502	602	<b>622</b>	Reassessed Signing, lighting and guarding
503	603	<b>623</b>	Reassessed Excavation in the highway
504	604	<b>624</b>	Reassessed Reinstatement and compaction of backfill materials
505	605	<b>625</b>	Reassessed Reinstatement of sub-base and base (roadbase) in non-bituminous materials
506	606	<b>626</b>	Reassessed Reinstatement in cold-lay bituminous materials
507	607	<b>627</b>	Reassessed Reinstatement in hot-lay bituminous materials
508	608	<b>628</b>	Reassessed Reinstatement of concrete slabs
509	609	<b>629</b>	Reassessed Reinstatement of modular surfaces and concrete footways
510	610	<b>630</b>	Reassessed Monitoring signing, lighting and guarding
511	611	<b>631</b>	Reassessed Monitoring excavation in the highway
512	612	<b>632</b>	Reassessed Monitoring reinstatement and compaction of backfill materials
513	613	<b>633</b>	Reassessed Monitoring reinstatement of sub-base and base (roadbase) in non-bituminous materials
514	614	<b>634</b>	Reassessed Monitoring reinstatement in bituminous materials
515	615	<b>635</b>	Reassessed Monitoring reinstatement of concrete slabs
516	616	<b>636</b>	Reassessed Monitoring reinstatement of modular surfaces and concrete footways